

DIVERSIFIED

TESTING LABORATORIES, INC.

WORLDWIDE SERVICE

-"We Test Per Your Request"———

336 WEST FRONT STREET P.O. BOX 4004 BURLINGTON, NORTH CAROLINA 27215 PHONE (336) 227-7710 • FAX (336) 227-1175 www.diversifiedtestinglabs.com

August 20, 2018

Ms. Angelika Schmidt-Koch DELIUS GMBH Goldstraβe 16 – 18 33602 Bielefeld Germany

Reference:

Laboratory Test Report

Lab Identification No. 31902

Invoice No. 63069

Dear Ms. Schmidt-Koch:

One (1) sample, identified as **ARTICLE GAVI 29352**, was received and tested in accordance with the Motor Vehicle Safety Standard No. 302. The results are as follows:

TEST RESULTS

The sample submitted stopped burning before it had burned for 60 seconds from the start of timing, and had not burned more than two (2) inches from the point where timing was started.

The sample submitted **meets** the minimum requirements of the above standard. Material cannot burn at a rate of more than 4.00 inches/minute.

If there are any questions or when we can be of further assistance, please let us know.

Sincerely,

Brian S. Dement

BSD/mr