

Intertek The Warehouse Brewery Lane Leigh WN7 2RJ UK Tel +44 1942 265 700 consumergoods.uk@intertek.com intertek.com

FLAMMABILITY TEST REPORT

Report No.: LEI18092189A	Date Received: 14/09/18	Date Tested: 20/09/18	Date Issued: 20/09/18
Company Name & Address:	DELIUS GMBH & CO. KG GOLDSTRAßE 16-18 33602 BIELEFELD GERMANY		
Contact Name:	P. BAUMHÖFNER		
Sample Details			
Reference No.:	Not stated		
Order No.:	641		
Style No.:	Not stated		
Batch No.:	Not stated		
Quality:	Watson		
Colour:	Not stated		
Supplier:	Delius GmbH & Co. KG		
End Use:	Drapes + Curtains		
Quoted Fibre Composition:	100% wool		
Retailer:	Not stated		
Buying Division:	Not stated		
Sample Description:	Brown coloured woven fabr	ic	

Test Method	Pre Treatment	Performance Requirement	Result
IMO FTP Code (2010) Annex 1, Part 7: Test for Vertically Orientated Support Textiles and Films	None – The scope states that "fabrics which are not inherently flame resistant should be exposed to cleaning or exposure procedures"	IMO FTP Code (2010) Annex 1, Part 7, Clause 3	PASS

Note: The fabric supplied was tested with no pre-treatments at the request of the customer. Please note: The testing was carried out in the ISO 6941 environment

ANDREW HALLETT

(Flammability Team Leader)

STEVEN OWEN (Technical & Operational Excellence Manager)

.....

Report No.: LEI18092189A Page 1 of 2

CAROLE SPOWART (Flammability Administrator)









FLAMMABILITY TEST REPORT

Additional Information (Annex)		
Name and Address of the Sponsor:	Not Stated	
Name and Address of the	Delius GmbH	
Manufacturer/Supplier (If known):		
Type of Furniture:	Not Stated	
Fabric Details – Weave/Density/Yarn	Not Stated	
count/thickness(mm)/mass(g/m ²) Colour &		
Tone:		
Fire Retardant Treatment:	No	
Test Specification		
Test Method:	IMO FTP Code (2010) Annex 1, Part 7	
Ignition Source:	40mm high Propane gas flame	
Ignition Type:	Face ignition (as determined by the pre-test)	
Flame Application Time:	15 seconds (as determined by the pre-test)	
Sample Size:	220 x 170mm	

Pre-treatment / Durability Procedure

None - At the request of the customer.

Conditioning Prior to Testing: At least 24 hours in an atmosphere having a temperature of 20±5°C. and a relative humidity of 65±5% Temperature between 15°C & 30°C. Relative humidity between 20% & 65%

Test Results

At Time of Testing:

Side Tested:

Report of tests carried out in accordance IMO FTP Code (2010) Annex 1, Part 7.

Face

"The test results relate to the behaviour of the test specimens of a product under the particular conditions of the test; they are not intended to be the sole criterion for assessing the potential fire hazard of the product in use."

Sample No./	Duration of	Duration of	Flaming	Flame to	Hole to edge	Maximum damaged length (mm)		Average Damage Length (mm)
Direction	flaming (Secs)	afterglow (Secs)	debris	edge		Horizontal	Vertical	Length (mm)
1. Length ↑	0.0	0.0	No	No	No	25	75	
2. Length ↓	0.0	0.0	No	No	No	27	85	
3. Length ↑	0.0	0.0	No	No	No	27	75	83.0
4. Length ↓	0.0	0.0	No	No	No	25	90	
5. Length ↑	0.0	0.0	No	No	No	25	90	
6. Width \rightarrow	0.0	0.0	No	No	No	25	82	
7. Width ←	0.0	0.0	No	No	No	25	88	
8. Width \rightarrow	0.0	0.0	No	No	No	26	77	82.4
9. Width ←	0.0	0.0	No	No	No	25	80	
10. Width \rightarrow	0.0	0.0	No	No	No	25	85	

This report is made solely on the basis of your instructions and/or information and materials supplied by you. It is not intended to be a recommendation for any particular course of action. Intertek does not accept a duty of care or any other responsibility to any person other than the Client in respect of this report and only accepts liability to the Client insofar as is expressly contained in the terms and conditions governing Intertek's provision of services to you. Intertek makes no warranties or representations either express or implied with respect to this report save as provided for in those terms and conditions. We have aimed to conduct the Review on a diligent and careful basis and we do not accept any liability to you for any loss arising out of or in connection with this report, in contract, tort, by statute or otherwise, except in the event of our gross negligence or willful misconduct.

Report No.: LEI18092189A Page 2 of 2

