



DIVERSIFIED
TESTING LABORATORIES, INC.
WORLDWIDE SERVICE

“We Test Per Your Request”

336 WEST FRONT STREET
P.O. BOX 4004
BURLINGTON, NORTH CAROLINA 27215
PHONE (336) 227-7710 • FAX (336) 227-1175
www.diversifiedtestinglabs.com

August 20, 2018

Ms. Angelika Schmidt-Koch
DELIUS GMBH
Goldstraße 16 – 18
33602 Bielefeld
Germany

Reference: Laboratory Test Report
Lab Identification No. 31902
Invoice No. 63069

Dear Ms. Schmidt-Koch:

One (1) sample, identified as **ARTICLE SABA 36857**, was received and tested in accordance with the Motor Vehicle Safety Standard No. 302. The results are as follows:

TEST RESULTS

The sample submitted stopped burning before it had burned for 60 seconds from the start of timing, and had not burned more than two (2) inches from the point where timing was started.

The sample submitted **meets** the minimum requirements of the above standard. Material cannot burn at a rate of more than 4.00 inches/minute.

If there are any questions or when we can be of further assistance, please let us know.

Sincerely,

Brian S. Dement

BSD/mr

